

MR & MRS JONES

Victoria House, South Street, Farnham, Surrey

Report by: John Doe


Report date: 01/01/2024



Issue number: 1

MAIN ROOF


Missing capping to fascia and soffit connector missing



Issue number: 2

SIDE ELEVATION

Earth wire missing clips and needs outlet sealed to stop insect infestation



Issue number: 3

KITCHEN


Door handle not fitted correctly



Issue number: 4

MASTER BEDROOM


Damage to wardrobe door, handle fitted incorrectly



Issue number: 5

KITCHEN

Sink tap loose



Issue number: 6

BATHROOM

Incorrect tap fitted, restrict level action.



Issue number: 7

Assigned to Master Bedroom Item 4

Poor fitting spotlight above bed post



Issue number: 8

REAR ELEVATION

Poor finish to brickwork

Issue number: 9

REAR ELEVATION

Seal between brick and pipe. To stop insect infestation.

